

FIG. 1




FIG. 2




FIG. 3




FIG. 4






FIG. 5

AMOUNT OF CHARGE IN
PHOTOSENSITIVE MEMBER
(ABSOLUTE VALUE)



DETERIORATION OF PHOTOSENSITIVE MEMBER
CONTAMINATION OF CHARGER WIRE

FIG. 6



F I G. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14





FIG. 15



F I G. 1 6

OPC COUNT [$\times 10^3$ cycle]	ESTIMATED FILM THINNING AMOUNT [μ m]	BIAS ADJUSTMENT VALUE [V]
0	0	0
4 0	1	- 1 0
8 0	2	- 2 0
1 2 0	3	- 3 0
1 6 0	4	- 4 0
2 0 0	5	- 5 0
2 4 0	6	- 6 0
2 8 0	7	- 7 0
3 2 0	8	- 8 0
3 6 0	9	- 9 0
4 0 0	1 0	- 1 0 0

FIG. 17




FIG. 18

